



"Solving Today's Problems with Tomorrow's Technologies"

21 Wilbraham Street, Box B11
Palmer, Massachusetts 01069 USA

Phone 413.284.0000
Fax 413.284.0300

Product Information Commonwealth of Massachusetts Bid Specifications

Project: Chicopee Housing Authority – Fairview Apartments

Additional Information: Balconies

Product(s): FOR PROFESSIONAL USE ONLY
Dyna-Pur 9051BL Coating
Dyna-Prime W-3 Primer (as needed)
HydraLok SLR-2 Crack Filler (as needed)

Product Information:

- **Dyna-Pur 9051BL Coating** is a two part pure polyurea brushable system
 - ✓ Cost per 2 gallon kit - Dyna-Pur 9051BL - \$300.
 - ✓ Coverage – 160 sq ft per gallon at 10 mil, and with 0% waste
 - ✓ Two coats of 10 mil are recommended
 - ✓ Aggregate is to be dispersed between coats for slip resistance at an application rate of ≥ 10 lbs / 100 sq ft
 - ✓ Contractors should budget 10% to 20% waste, based upon application technique and experience
 - ✓ MSDS for Dyna-Pur 9051BL Series available at www.dynasolv.com/
- **Dyna-Prime W-3 Primer** is a two part waterborne epoxy primer
 - ✓ Cost per 2 gallon kit – Dyna-Prime W-3 Primer - \$109.
 - ✓ Coverage – 200-250 sq ft per gallon
- **HydraLok SLR-2 Crack Filler** is a two part pure polyurea crack filler
 - ✓ Cost per 600 ml. (300 ml. X 300 ml.) dual component cartridge – \$42.25 unpigmented; \$48.75 gray (single unit price)
 - ✓ Cost per case of 12 – 600 ml. dual component cartridges – \$390. unpigmented; \$450. gray (case price)
 - ✓ Coverage – 48 linear ft per cartridge at $\frac{1}{4}$ by $\frac{1}{4}$ inch crack fill
 - ✓ Two component Manual Dispenser is available for \$99.

Application Training – Dyna-Pur 9051BL Series Installer Application Training:

- Application training is recommended
 - ✓ Minimize application waste
 - ✓ Validates product warranty *
 - ✓ Reduce job failure(s)
 - ✓ Save time and money
- Training information
 - ✓ Duration: 3 hours
 - ✓ Cost: \$250. per person
 - ✓ Cost includes materials, training, and disposables used during training
 - ✓ 2 people in attendance minimum per company

* Manufacturer offers no product warranty for installations by installers that have not successfully completed the Dyna-Pur 9051BL Series Installer Application Training.